




Period: 9-01-2021 to 15-01-2021

Calibration	Eureka Manta Multiparameter probe		
	S/N: MT12183556	Calibration Date: 09/01/2021	Status: Used for measurements
	S/N: MT12183554	Calibration Date: N/A	Status: Spare

Location ID	Description
W2	Reclamation
W5	
W7	
W10	
W11	
W14	Villigili
W15	
W16	Reclamation
W19	Background
W20	Borrow area
W25	
W26	
W27	Background
W36	Borrow area
W45	
W46	
W47	
W51	

Signed by Client

Project	: Dredging, Land Reclamation and Revetment Works at Gulihafalu	Document number	: 462.10062-WQR-34.2
Contract number	: AGR(471)-PIDS/PR/IV/2019/194	Contractor	: Boskalis Westminster Contracting Ltd
Project number [MIAS]	: 462.10042	Client	: Ministry of National Planning and Infrastructure
		Attention	shaana.farooq@planning.gov.mv





WATER QUALITY REPORT

Dredging, Land Reclamation and Revetment Works at Gulhifalhu



Date: 09-01-2021

Time: 7:20 to 9:30


Project : Dredging, Land Reclamation and Revetment Works at Gulhifalhu □ Document number : 462.10062-WQR-34.4
Contract number : AGR(471)-PIDS2/PRIV/2019/194 Contractor : Boskalis Westminster Contracting Ltd
Project number [MIAS] : 462.10042 Client : Ministry of National Planning and Infrastructure
Attention : shaana.farooq@planning.gov.mv

Results

Location	Section	Depth (m)	Temperature (°C)	pH	Conductivity (uS/cm)	Turbidity (NTU)
W2	Surface	1	28.6	6.5	51258	-0.12
	Mid-water	11	28.5	6.4	51377	-0.11
	Bottom	23	28.5	6.3	51547	-0.11
W5	Surface	1	28.6	4.2	51169	-0.02
	Mid-water	12	28.5	4.2	51459	-0.08
	Bottom	23	28.4	4.3	51652	-0.07
W7	Surface	1	28.6	4.4	51135	-0.06
	Mid-water	12	28.6	4.4	51179	-0.10
	Bottom	24	28.5	4.5	51676	-0.07
W10	Surface	1	28.6	5.0	51220	-0.05
	Mid-water	12	28.6	4.9	51336	-0.08
	Bottom	23	28.5	4.9	51682	-0.07
W11	Surface	1	28.7	5.3	51178	-0.06
	Mid-water	11	28.6	5.1	51232	-0.09
	Bottom	24	28.5	5.2	51506	-0.07
W14	Surface	1	28.7	6.6	51219	0.00
	Mid-water	8	28.6	6.6	51191	0.04
	Bottom	17	28.6	6.5	51207	0.02
W15	Surface	1	28.6	4.6	51098	-0.11
	Mid-water	12	28.6	5.0	51079	-0.11
	Bottom	23	28.5	5.4	51504	-0.06
W16	Surface	1	28.7	6.3	51207	-0.06
	Mid-water	12	28.6	6.1	51279	-0.09
	Bottom	23	28.5	6.1	51343	-0.10
W19	Surface					
	Mid-water					
	Bottom					
W20	Surface					
	Mid-water					
	Bottom					
W25	Surface					
	Mid-water					
	Bottom					
W26	Surface					
	Mid-water					
	Bottom					
W27	Surface					
	Mid-water					
	Bottom					
W36	Surface					
	Mid-water					
	Bottom					
W45	Surface					
	Mid-water					
	Bottom					
W46	Surface					
	Mid-water					
	Bottom					
W47	Surface					
	Mid-water					
	Bottom					
W51	Surface					
	Mid-water					
	Bottom					

Vessel	Stop	Start

Tides




Remarks

Fairway completed the dredging phase of the works on the 20th of August, therefore as of the 25th only the Reclamation area locations are measured

Water samples taken from all reclamation sites for TSS testing

Calibrated Manta Probe





WATER QUALITY REPORT

Dredging, Land Reclamation and Revetment Works at Gulhifalhu




Date: 10-01-2021

Time: 8:00 to 10:00


Project : Dredging, Land Reclamation and Revetment Works at Gulhifalhu □ Document number : 462.10062-WQR-34.5
Contract number : AGR(471)-PIDS2/PRIV/2019/194 Contractor : Boskalis Westminster Contracting Ltd
Project number [MIAS] : 462.10042 Client : Ministry of National Planning and Infrastructure
Attention : shaana.farooq@planning.gov.mv

Location	Section	Depth (m)	Temperature (°C)	pH	Conductivity (uS/cm)	Turbidity (NTU)
W2	Surface	1	28.6	7.4	51340	-0.18
	Mid-water	12	28.5	7.3	51559	-0.21
	Bottom	23	28.5	7.3	51796	-0.11
W5	Surface	1	28.6	6.3	51220	-0.21
	Mid-water	11	28.5	6.7	51381	-0.20
	Bottom	22	28.5	6.5	51738	-0.11
W7	Surface	1	28.6	6.9	51275	-0.13
	Mid-water	12	28.6	6.7	51459	-0.19
	Bottom	23	28.5	6.7	51513	-0.16
W10	Surface	1	28.6	7.1	51465	-0.22
	Mid-water	12	28.6	7.1	51458	-0.21
	Bottom	22	28.5	7.1	51500	-0.20
W11	Surface	1	28.5	7.2	51519	-0.16
	Mid-water	12	28.5	7.2	51480	-0.20
	Bottom	23	28.5	7.2	51499	-0.17
W14	Surface	1	28.7	7.4	51302	-0.09
	Mid-water	8	28.7	7.4	51291	0.21
	Bottom	17	28.6	7.4	51315	0.61
W15	Surface	1	28.6	5.9	51146	-0.23
	Mid-water	12	28.6	6.2	51170	-0.23
	Bottom	24	28.6	6.4	51423	-0.21
W16	Surface	1	28.6	7.3	51287	-0.21
	Mid-water	12	28.6	7.2	51376	-0.17
	Bottom	21	28.5	7.2	51558	-0.14
W19	Surface					
	Mid-water					
	Bottom					
W20	Surface					
	Mid-water					
	Bottom					
W25	Surface					
	Mid-water					
	Bottom					
W26	Surface					
	Mid-water					
	Bottom					
W27	Surface					
	Mid-water					
	Bottom					
W36	Surface					
	Mid-water					
	Bottom					
W45	Surface					
	Mid-water					
	Bottom					
W46	Surface					
	Mid-water					
	Bottom					
W47	Surface					
	Mid-water					
	Bottom					
W51	Surface					
	Mid-water					
	Bottom					

Stoppages	Vessel	Stop	Start



Fairway completed the dredging phase of the works on the 20th of August, therefore as of the 25th only the Reclamation area locations are measured





WATER QUALITY REPORT

Dredging, Land Reclamation and Revetment Works at Gulhifalhu



Date: 11-01-2021

Time: 8:10 to 10:20

Project : Dredging, Land Reclamation and Revetment Works at Gulhifalhu □ Document number : 462.10062-WQR-34.6
Contract number : AGR(471)-PIDS2/PRIV/2019/194 Contractor : Boskalis Westminster Contracting Ltd
Project number [MIAS] : 462.10042 Client : Ministry of National Planning and Infrastructure
Attention : shaana.farooq@planning.gov.mv


Results

Location	Section	Depth (m)	Temperature (°C)	pH	Conductivity (uS/cm)	Turbidity (NTU)
W2	Surface	1	28.5	7.4	51573	-0.20
	Mid-water	12	28.5	7.5	51630	-0.21
	Bottom	23	28.5	7.3	51885	-0.16
W5	Surface	1	28.5	5.3	51718	-0.04
	Mid-water	12	28.5	5.3	51792	-0.10
	Bottom	20	28.5	5.3	51977	0.06
W7	Surface	1	28.6	6.6	51545	-0.03
	Mid-water	12	28.6	6.5	51527	-0.18
	Bottom	23	28.6	6.5	51657	-0.19
W10	Surface	1	28.6	6.8	51500	-0.19
	Mid-water	11	28.6	6.8	51479	-0.19
	Bottom	19	28.5	6.7	51695	-0.20
W11	Surface	1	28.5	7.0	51619	-0.20
	Mid-water	12	28.5	7.1	51620	-0.20
	Bottom	22	28.5	7.0	51693	-0.19
W14	Surface	1	28.7	7.6	51546	-0.09
	Mid-water	8	28.6	7.5	51542	0.06
	Bottom	18	28.6	7.5	51599	0.31
W15	Surface	1	28.5	5.3	51580	-0.20
	Mid-water	12	28.6	5.5	51663	-0.21
	Bottom	25	28.6	5.8	51640	-0.21
W16	Surface	1	28.6	7.4	51548	-0.21
	Mid-water	11	28.6	7.4	51562	-0.19
	Bottom	18	28.6	7.3	51556	-0.19
W19	Surface					
	Mid-water					
	Bottom					
W20	Surface					
	Mid-water					
	Bottom					
W25	Surface					
	Mid-water					
	Bottom					
W26	Surface					
	Mid-water					
	Bottom					
W27	Surface					
	Mid-water					
	Bottom					
W36	Surface					
	Mid-water					
	Bottom					
W45	Surface					
	Mid-water					
	Bottom					
W46	Surface					
	Mid-water					
	Bottom					
W47	Surface					
	Mid-water					
	Bottom					
W51	Surface					
	Mid-water					
	Bottom					

Stoppages


Vessel	Stop	Start

Tides



Remarks

Fairway completed the dredging phase of the works on the 20th of August, therefore as of the 25th only the Reclamation area locations are measured





WATER QUALITY REPORT

Dredging, Land Reclamation and Revetment Works at Gulhifalhu



Date: 12-01-2021

Time: 7:10 to 10:10

Project : Dredging, Land Reclamation and Revetment Works at Gulhifalhu □ Document number : 462.10062-WQR-34.7
Contract number : AGR(471)-PIDS2/PRIV/2019/194 Contractor : Boskalis Westminster Contracting Ltd
Project number [MIAS] : 462.10042 Client : Ministry of National Planning and Infrastructure
Attention : shaana.farooq@planning.gov.mv


Results

Location	Section	Depth (m)	Temperature (°C)	pH	Conductivity (uS/cm)	Turbidity (NTU)
W2	Surface	1	28.3	7.6	50192	-0.12
	Mid-water	12	28.5	7.6	51315	-0.18
	Bottom	23	28.5	7.6	51317	-0.16
W5	Surface	1	28.4	5.9	51214	0.33
	Mid-water	12	28.4	5.7	51792	0.35
	Bottom	23	28.3	5.8	51974	0.46
W7A	Surface	1	28.4	6.4	51474	-0.05
	Mid-water	12	28.4	6.4	51552	-0.07
	Bottom	21	28.4	6.3	51577	-0.08
W10	Surface	1	28.4	7.1	51377	-0.14
	Mid-water	11	28.5	7.0	51348	-0.16
	Bottom	16	28.4	7.0	51466	-0.15
W11	Surface	1	28.4	7.3	51337	-0.05
	Mid-water	11	28.4	7.3	51313	-0.17
	Bottom	24	28.4	7.2	51543	-0.14
W14	Surface	1	28.5	8.9	51229	-0.07
	Mid-water	8	28.5	9.6	51316	-0.01
	Bottom	17	28.5	10.5	51321	0.44
W15	Surface	1	28.5	5.2	51463	-0.19
	Mid-water	12	28.5	5.3	51633	-0.16
	Bottom	24	28.5	5.7	51824	-0.13
W16	Surface	1	28.3	7.6	50889	-0.17
	Mid-water	11	28.5	7.6	51486	-0.18
	Bottom	23	28.5	7.7	51533	-0.15
W19	Surface					
	Mid-water					
	Bottom					
W20	Surface					
	Mid-water					
	Bottom					
W25	Surface					
	Mid-water					
	Bottom					
W26	Surface					
	Mid-water					
	Bottom					
W27	Surface					
	Mid-water					
	Bottom					
W36	Surface					
	Mid-water					
	Bottom					
W45	Surface					
	Mid-water					
	Bottom					
W46	Surface					
	Mid-water					
	Bottom					
W47	Surface					
	Mid-water					
	Bottom					
W51	Surface					
	Mid-water					
	Bottom					

Stoppages


Vessel	Stop	Start

Tides



Remarks

Fairway completed the dredging phase of the works on the 20th of August, therefore as of the 25th only the Reclamation area locations are measured





WATER QUALITY REPORT

Dredging, Land Reclamation and Revetment Works at Gulhifalhu



Date: 13-01-2021

Time: 8:10 to 10:30

Project : Dredging, Land Reclamation and Revetment Works at Gulhifalhu □ Document number : 462.10062-WQR-34.8
Contract number : AGR(471)-PIDS2/PRIV/2019/194 Contractor : Boskalis Westminster Contracting Ltd
Project number [MIAS] : 462.10042 Client : Ministry of National Planning and Infrastructure
Attention : shaana.farooq@planning.gov.mv


Results

Location	Section	Depth (m)	Temperature (°C)	pH	Conductivity (uS/cm)	Turbidity (NTU)
W2	Surface	1	28.4	7.6	51603	-0.14
	Mid-water	11	28.4	7.6	51565	-0.12
	Bottom	21	28.4	7.7	51573	-0.08
W5	Surface	1	28.3	6.3	51700	0.09
	Mid-water	12	28.3	6.0	51828	0.11
	Bottom	21	28.2	6.1	52174	0.21
W7	Surface	1	28.3	7.2	51625	0.06
	Mid-water	12	28.3	7.1	51616	-0.05
	Bottom	21	28.3	7.1	51633	-0.13
W10	Surface	2	28.3	7.5	51774	-0.12
	Mid-water	11	28.3	7.5	51799	-0.11
	Bottom	21	28.3	7.4	52027	-0.13
W11	Surface	1	28.4	7.7	51623	-0.11
	Mid-water	12	28.3	7.6	51664	-0.10
	Bottom	23	28.3	7.6	51646	-0.12
W14	Surface	1	28.3	7.7	51468	0.03
	Mid-water	8	28.3	7.7	51450	0.05
	Bottom	15	28.3	7.7	51503	0.12
W15	Surface	1	28.3	5.7	51621	-0.15
	Mid-water	11	28.4	5.7	51660	-0.13
	Bottom	23	28.4	5.7	51621	-0.13
W16	Surface	1	28.4	7.7	51621	-0.10
	Mid-water	11	28.4	7.7	51613	-0.12
	Bottom	23	28.4	7.7	51651	-0.07
W19	Surface					
	Mid-water					
	Bottom					
W20	Surface					
	Mid-water					
	Bottom					
W25	Surface					
	Mid-water					
	Bottom					
W26	Surface					
	Mid-water					
	Bottom					
W27	Surface					
	Mid-water					
	Bottom					
W36	Surface					
	Mid-water					
	Bottom					
W45	Surface					
	Mid-water					
	Bottom					
W46	Surface					
	Mid-water					
	Bottom					
W47	Surface					
	Mid-water					
	Bottom					
W51	Surface					
	Mid-water					
	Bottom					

Stoppages


Vessel	Stop	Start

Tides



Remarks

Fairway completed the dredging phase of the works on the 20th of August, therefore as of the 25th only the Reclamation area locations are measured





WATER QUALITY REPORT

Dredging, Land Reclamation and Revetment Works at Gulhifalhu




Date: 14-01-2021

Time: 9:30 to 11:50


Project : Dredging, Land Reclamation and Revetment Works at Gulhifalhu □ Document number : 462.10062-WQR-34.9
Contract number : AGR(471)-PIDS2/PRIV/2019/194 Contractor : Boskalis Westminster Contracting Ltd
Project number [MIAS] : 462.10042 Client : Ministry of National Planning and Infrastructure
Attention : shaana.farooq@planning.gov.mv

Location	Section	Depth (m)	Temperature (°C)	pH	Conductivity (uS/cm)	Turbidity (NTU)
W2	Surface	1	28.4	7.2	51657	0.11
	Mid-water	12	28.4	7.2	51739	-0.08
	Bottom	21	28.3	7.1	52028	-0.06
W5	Surface	1	28.3	5.6	51800	0.00
	Mid-water	11	28.3	5.5	51803	-0.04
	Bottom	17	28.2	5.4	52075	0.02
W7	Surface	1	28.4	6.2	51727	-0.14
	Mid-water	12	28.3	6.1	51684	-0.14
	Bottom	22	28.3	6.1	51780	-0.10
W10	Surface	1	28.4	6.7	51699	-0.17
	Mid-water	11	28.4	6.7	51664	-0.14
	Bottom	24	28.3	6.6	51769	-0.16
W11	Surface	1	28.5	7.0	51702	-0.17
	Mid-water	11	28.4	6.9	51689	-0.15
	Bottom	17	28.3	6.9	51784	-0.16
W14	Surface	1	28.4	7.3	51684	-0.04
	Mid-water	8	28.3	7.2	51635	0.05
	Bottom	17	28.2	7.2	51631	0.58
W15	Surface	1	28.4	5.4	51614	-0.15
	Mid-water	12	28.3	5.7	51573	-0.12
	Bottom	23	28.3	6.1	51647	-0.12
W16	Surface	1	28.5	7.1	51719	-0.12
	Mid-water	12	28.4	7.0	51676	-0.14
	Bottom	24	28.3	7.0	51711	-0.10
W19	Surface					
	Mid-water					
	Bottom					
W20	Surface					
	Mid-water					
	Bottom					
W25	Surface					
	Mid-water					
	Bottom					
W26	Surface					
	Mid-water					
	Bottom					
W27	Surface					
	Mid-water					
	Bottom					
W36	Surface					
	Mid-water					
	Bottom					
W45	Surface					
	Mid-water					
	Bottom					
W46	Surface					
	Mid-water					
	Bottom					
W47	Surface					
	Mid-water					
	Bottom					
W51	Surface					
	Mid-water					
	Bottom					

Stoppages	Vessel	Stop	Start



Fairway completed the dredging phase of the works on the 20th of August, therefore as of the 25th only the Reclamation area locations are measured





WATER QUALITY REPORT

Dredging, Land Reclamation and Revetment Works at Gulhifalhu




Date: 15-01-2021

Time: 8:10 to 10:20


Project : Dredging, Land Reclamation and Revetment Works at Gulhifalhu □ Document number : 462.10062-WQR-34.10
Contract number : AGR(471)-PIDS2/PRIV/2019/194 Contractor : Boskalis Westminster Contracting Ltd
Project number [MIAS] : 462.10042 Client : Ministry of National Planning and Infrastructure
Attention : shaana.farooq@planning.gov.mv

Location	Section	Depth (m)	Temperature (°C)	pH	Conductivity (uS/cm)	Turbidity (NTU)
W2	Surface	1	28.4	7.5	52027	-0.13
	Mid-water	12	28.3	7.5	52100	-0.10
	Bottom	22	28.2	7.4	52231	-0.07
W5	Surface	1	28.3	5.6	51997	-0.09
	Mid-water	12	28.2	5.5	52219	-0.04
	Bottom	18	28.1	5.5	52341	-0.08
W7	Surface	1	28.3	6.0	52135	0.00
	Mid-water	12	28.2	6.0	52123	-0.07
	Bottom	24	28.2	5.9	52299	-0.11
W10	Surface	1	28.3	6.7	51970	-0.04
	Mid-water	12	28.3	6.6	52026	-0.12
	Bottom	22	28.3	6.6	52047	-0.15
W11	Surface	1	28.4	7.1	52002	-0.11
	Mid-water	11	28.3	6.9	52196	-0.12
	Bottom	23	28.2	6.8	52277	-0.05
W14	Surface	1	28.5	7.7	51795	0.00
	Mid-water	8	28.4	7.6	51824	-0.08
	Bottom	17	28.4	7.6	51868	0.08
W15	Surface	1	28.4	5.6	51823	-0.12
	Mid-water	12	28.3	6.0	51921	-0.10
	Bottom	19	28.3	6.3	51909	-0.10
W16	Surface	1	28.5	7.4	51955	-0.07
	Mid-water	9	28.4	7.3	51872	-0.11
	Bottom	16	28.4	7.3	51918	-0.12
W19	Surface					
	Mid-water					
	Bottom					
W20	Surface					
	Mid-water					
	Bottom					
W25	Surface					
	Mid-water					
	Bottom					
W26	Surface					
	Mid-water					
	Bottom					
W27	Surface					
	Mid-water					
	Bottom					
W36	Surface					
	Mid-water					
	Bottom					
W45	Surface					
	Mid-water					
	Bottom					
W46	Surface					
	Mid-water					
	Bottom					
W47	Surface					
	Mid-water					
	Bottom					
W51	Surface					
	Mid-water					
	Bottom					

Stoppages	Vessel	Stop	Start



Fairway completed the dredging phase of the works on the 20th of August, therefore as of the 25th only the Reclamation area locations are measured



Male' Water & Sewerage Company Pvt Ltd**Water Quality Assurance Laboratory**

Quality Assurance Building, 1st Floor, Male' Hingun, Vilimale', Male' City, Maldives
Tel: +9603323209, Fax: +9603324306, Email: wqa@mwsc.com.mv

**LB-TEST-090****WATER QUALITY TEST REPORT****Report No: 500185860****Customer Information:**

CDE Pvt Ltd
H.Orchidmaage, 4th Floor
Ameeru Ahmed Magu
Male K

Report date: **19/01/2021**Test Requisition Form No: **900191011**Sample(s) Recieved Date: **17/01/2021**Date of Analysis: **17/01/2021 - 17/01/2021**

Sample Description ~	GF_REC-W15	GF_REC-W05	GF_REC-W07	TEST METHOD	UNIT
Sample Type ~	Sea Water	Sea Water	Sea Water		
Sample No	83215943	83215944	83215945		
Sampled Date ~	09/01/2021 07:34	09/01/2021 07:47	09/01/2021 08:09		
PARAMETER	ANALYSIS RESULT				
Physical Appearance	Clear with particles	Clear with particles	Clear with particles		
Total Suspended Solids	<5 (LoQ 5 mg/L)	<5 (LoQ 5 mg/L)	<5 (LoQ 5 mg/L)	HACH Method 8006	mg/L

Keys: mg/L : Milligram Per Liter**Checked by**

Aminath Sofa
Laboratory Executive

Approved by

Mohamed Eyman
Manager, Quality

Notes: Sampling Authority: Sampling was not done by MWSC Laboratory

This report shall not be reproduced except in full, without written approval of MWSC

This test report is ONLY FOR THE SAMPLES TESTED.

~ Information provided by the customer

Male' Water & Sewerage Company Pvt Ltd**Water Quality Assurance Laboratory**

Quality Assurance Building, 1st Floor, Male' Hingun, Vilimale', Male' City, Maldives
Tel: +9603323209, Fax: +9603324306, Email: wqa@mwsc.com.mv

**LB-TEST-090****WATER QUALITY TEST REPORT**

Report No: 500185860

Customer Information:

CDE Pvt Ltd
H.Orchidmaage, 4th Floor
Ameeru Ahmed Magu
Male K

Report date: 19/01/2021

Test Requisition Form No: 900191011

Sample(s) Received Date: 17/01/2021

Date of Analysis: 17/01/2021 - 17/01/2021

Sample Description ~	GF_REC-W10	GF_REC-W11	GF_REC-W16	TEST METHOD	UNIT
Sample Type ~	Sea Water	Sea Water	Sea Water		
Sample No	83215946	83215947	83215948		
Sampled Date ~	09/01/2021 08:25	09/01/2021 08:36	09/01/2021 08:53		
PARAMETER	ANALYSIS RESULT				
Physical Appearance	Clear with particles	Clear with particles	Clear with particles	HACH Method 8006	mg/L
Total Suspended Solids	<5 (LoQ 5 mg/L)	<5 (LoQ 5 mg/L)	<5 (LoQ 5 mg/L)		

Keys: mg/L : Milligram Per Liter

Checked by

Aminath Sofa
Laboratory Executive

Approved by

Mohamed Eyman
Manager, Quality

Notes: Sampling Authority: Sampling was not done by MWSC Laboratory

This report shall not be reproduced except in full, without written approval of MWSC

This test report is ONLY FOR THE SAMPLES TESTED.

~ Information provided by the customer

Male' Water & Sewerage Company Pvt Ltd**Water Quality Assurance Laboratory**

Quality Assurance Building, 1st Floor, Male' Hingun, Vilimale', Male' City, Maldives
Tel: +9603323209, Fax: +9603324306, Email: wqa@mwsc.com.mv

**LB-TEST-090****WATER QUALITY TEST REPORT****Report No: 500185860****Customer Information:**

CDE Pvt Ltd
H.Orchidmaage, 4th Floor
Ameeru Ahmed Magu
Male K

Report date: **19/01/2021**Test Requisition Form No: **900191011**Sample(s) Received Date: **17/01/2021**Date of Analysis: **17/01/2021 - 17/01/2021**

Sample Description ~	GF_REC-W02	GF_REC-W14	TEST METHOD	UNIT
Sample Type ~	Sea Water	Sea Water		
Sample No	83215949	83215950		
Sampled Date ~	09/01/2021 09:07	09/01/2021 09:17		
PARAMETER	ANALYSIS RESULT			
Physical Appearance	Clear with particles	Clear with particles	HACH Method 8006	mg/L
Total Suspended Solids	<5 (LoQ 5 mg/L)	<5 (LoQ 5 mg/L)		

Keys: mg/L : Milligram Per Liter**Checked by**

Aminath Sofa
Laboratory Executive

Approved by

Mohamed Eyman
Manager, Quality

Notes: Sampling Authority: Sampling was not done by MWSC Laboratory

This report shall not be reproduced except in full, without written approval of MWSC

This test report is ONLY FOR THE SAMPLES TESTED.

~ Information provided by the customer

***** END OF REPORT *****